October 16, 2003

Mr. Lew W. Myers Chief Operating Officer FirstEnergy Nuclear Operating Company Davis-Besse Nuclear Power Station 5501 North State Route 2 Oak Harbor, OH 43449-9760

SUBJECT: DAVIS-BESSE NUCLEAR POWER STATION, UNIT 1 - RESPONSE TO NUCLEAR REGULATORY COMMISSION (NRC) BULLETIN 2003-01, "POTENTIAL IMPACT OF DEBRIS BLOCKAGE ON EMERGENCY SUMP RECIRCULATION AT PRESSURIZED-WATER REACTORS" (TAC NO. MB9572)

Dear Mr. Myers:

This letter acknowledges receipt of your response dated August 8, 2003, to NRC Bulletin 2003-01, "Potential Impact of Debris Blockage on Emergency Sump Recirculation at Pressurized-Water Reactors," dated July 9, 2003. The NRC issued Bulletin 2003-01 to all pressurized-water reactor licensees requesting that they provide a response, within 60 days of the date of Bulletin 2003-01, that contains either the information requested in the following Option 1 or Option 2 stated in Bulletin 2003-01:

- Option 1: State that the emergency core cooling system (ECCS) and containment spray system (CSS) recirculation functions have been analyzed with respect to the potentially adverse post-accident debris blockage effects identified in this bulletin, taking into account the recent research findings described in the Discussion section, and are in compliance with all existing applicable regulatory requirements.
- Option 2: Describe any interim compensatory measures that have been implemented or that will be implemented to reduce the risk which may be associated with potentially degraded or nonconforming ECCS and CSS recirculation functions until an evaluation to determine compliance is complete. If any of the interim compensatory measures listed in the Discussion section will not be implemented, provide a justification. Additionally, for any planned interim measures that will not be in place prior to your response to this bulletin, submit an implementation schedule and provide the basis for concluding that their implementation is not practical until a later date.

You provided an Option 1 response. Based on your response, the NRC staff considers your actions to be complete with regard to Bulletin 2003-01. Please retain any records of your actions in response to Bulletin 2003-01, as the NRC staff may conduct subsequent inspection activities regarding this issue. As noted in Bulletin 2003-01, the NRC staff recognizes that it may be necessary for addressees to undertake complex evaluations to determine whether regulatory compliance exists in light of the concerns identified in this bulletin. Therefore, the

L. Myers - 2 -

staff has not made a determination with regard to whether addressees are in compliance with the regulations. The staff is preparing a generic letter to request additional information regarding this issue, which will require your confirmatory evaluation in response.

Should you have any questions, please contact me at 301-415-3027 or the lead PM for this issue, John G. Lamb, at 301-415-1446.

Sincerely,

/RA by Carol F. Lyon for/

Jon B. Hopkins, Senior Project Manager, Section 2 Project Directorate III Division of Licensing Project Management Office of Nuclear Reactor Regulation

Docket No. 50-346

cc: See next page

L. Myers - 2 -

October 16, 2003

staff has not made a determination with regard to whether addressees are in compliance with the regulations. The staff is preparing a generic letter to request additional information regarding this issue, which will require your confirmatory evaluation in response.

Should you have any questions, please contact me at 301-415-3027 or the lead PM for this issue, John G. Lamb, at 301-415-1446.

Sincerely,

/RA by Carl F. Lyon for/

Jon B. Hopkins, Senior Project Manager, Section 2 Project Directorate III Division of Licensing Project Management Office of Nuclear Reactor Regulation

Docket No. 50-346

cc: See next page

DISTRIBUTION:

PUBLICPDIII-2 r/fWRulandAMendiolaFLyonTHarrisJLambJHopkinsOGCACRSCLipa, RIIIJLehning

RArchitzel TYChang

ADAMS Accession Number: ML032530018 *Previously concurred

OFFICE	PM:PDIII-2	LA:PDIII-2	SC:SPLB	SC:PDIII-2	D:PDIII
NAME	FLyon for, JHopkins	THarris*	SWeerakkody*	AMendiola	WRuland
DATE	10/14/03	9/11/03	9/19/03	10/15/03	10/16/03

Davis-Besse Nuclear Power Station, Unit 1

CC:

Mary E. O'Reilly FirstEnergy Corporation 76 South Main St. Akron, OH 44308

Manager - Regulatory Affairs First Energy Nuclear Operating Company Davis-Besse Nuclear Power Station Oak Harbor, OH 43449-9760

Director
Ohio Department of Commerce
Division of Industrial Compliance
Bureau of Operations & Maintenance
6606 Tussing Road
P.O.Box 4009
Reynoldsburg, OH 43068-9009

Regional Administrator U.S. Nuclear Regulatory Commission 801 Warrenville Road Lisle, IL 60523-4351

Michael A. Schoppman Framatome ANP 1911 N. Ft. Myer Drive Rosslyn, VA 22209

Resident Inspector U.S. Nuclear Regulatory Commission 5503 North State Route 2 Oak Harbor, OH 43449-9760

Plant Manager, Randel J. Fast FirstEnergy Nuclear Operating Company Davis-Besse Nuclear Power Station 5501 North State - Route 2 Oak Harbor, OH 43449-9760

Dennis Clum
Radiological Assistance Section Supervisor
Bureau of Radiation Protection
Ohio Department of Health
P.O. Box 118
Columbus, OH 43266-0118

Carol O'Claire, Chief, Radiological Branch Ohio Emergency Management Agency 2855 West Dublin Granville Road Columbus, OH 43235-2206

Zack A. Clayton
DERR
Ohio Environmental Protection Agency
P.O. Box 1049
Columbus, OH 43266-0149

State of Ohio Public Utilities Commission 180 East Broad Street Columbus, OH 43266-0573

Attorney General Department of Attorney 30 East Broad Street Columbus, OH 43216

President, Board of County Commissioners of Ottawa County Port Clinton, OH 43252

President, Board of County Commissioners of Lucas County One Government Center, Suite 800 Toledo, OH 43604-6506

David Lochbaum, Nuclear Safety Engineer Union of Concerned Scientists 1707 H Street NW, Suite 600 Washington, DC 20006

The Honorable Dennis J. Kucinich United States House of Representatives Washington, DC 20515

The Honorable Dennis J. Kucinich, Member United States House of Representatives 14400 Detroit Avenue Lakewood, OH 44107